

1/10




FIG.1




FIG.3

20071109 54294001

2/10




FIG.2

3/10


402

WREXPERT

File Import Injury Library Analysis Options Database Maintenance Feedback Help

☒ Data Sources 
 ☒ Claimant Data 
 ☒ Vehicle Data 
 ☒ Accident Data 
 Damage Data 
 Crush Data

Click on components listed on repair estimate by moving cursor to part and clicking left mouse button. Also indicate which parts have visible damage.



Chevrolet Camaro

Side	Component	Repair/Replace
	bumper cover	replaced
	mounting brackets	replaced
	impact bar	replaced

☐ Estimate Complete

FIG.4A


404

WREXPERT

File Import Injury Library Analysis Options Database Maintenance Feedback Help

☒ Data Sources 
 ☒ Claimant Data 
 ☒ Vehicle Data 
 ☒ Accident Data 
 Damage Data 
 Crush Data

Click on components listed on repair estimate by moving cursor to part and clicking left mouse button. Also indicate which parts have visible damage.



Nissan Sentra E

Side	Component	Visible Damage

☐ Estimate Complete

FIG.4B

4/10




FIG. 5

5/10

Winoper-Smith, John 1

☐ ☐ ☐

File Import Injury Library Analysis Options Database Options Feedback Help

☒ Vehicles ☒ Claimant ☒ Configuration ☒ Suburban ☒ Mazda ☐ Crush

☐ Crush Description ☐ Crush Questions

Indicate the absence/presence of crush via the Damage type selections. If crush is indicated then enter the amount, in inches via the keyboard or the mouse. Left mouse will add crush. Right mouse will reduce crush.

Damage Type

☐ No Crush  
☒ Crush

Selection Width 8.2"

Overhang N/A

Examples

Crush by Sector

Edit Induced

Damage Type

☐ No Crush  
☒ Crush

Inches of Crush Depth

A	B	C	D	E	F	G	H
---	---	---	---	---	---	---	---

Chevrolet Suburban C20

Crush Damage Location

ABCDEFGH

Mazda Miata

You have Indicate No Crush for this Vehicle. Data Entry is not Required.

FIG. 5A

6/10




FIG. 6

7/10

710

WREXPRT

File

Import

Injury Library

Analysis Options

Database Maintenance

Feedback

Help

Data Sources

Claimant Data

Vehicle Data

Accident Data

Damage Data

Crash Data

Question

7. The induced damage was on which side of the Mazda Miata (looking from the driver's viewpoint)?

Answer Selection

driver side

passenger side

both

Why?

Exit Q/A

Restart

From the Q and A History, select the question to restart. Select the Restart button

Restart

Q and A History

#	Question	Answer
1	Do either of the vehicles have any modifications which would	no
2	Were either of the vehicles towing a trailer or another object?	no
3	Does the claimant's Mazda Miata have any visible damage	yes
4	Was the damage to then claimant's Mazda Miata caused	no

FIG. 7A

8/10




FIG. 7B



9/10




FIG.8




FIG.9

10/10




FIG. 10